


# How to connect a laptop to the 3M Wall Display Board



1. Connect the PC audio cable **1** to the headphones jack on the laptop.



2. Connect the VGA cable **2** to the VGA/Monitor port on the laptop.



3. Connect the USB cable **3** to the USB port on the laptop.

Any problem please call Customer Services at extension 3340.

For full interactive 3M Digital Wall Display, please contact FCPE at extension 4220 to have the Ebeam software installed.